


ANATOMY DIAGRAM & PARTS LIST

GRAINFATHER



LIST OF PARTS



HI, I'M THE G40
& HERE ARE ALL
OF MY PARTS



1	G40 Glass Lid	10907
2	G40 Support Ring	10900
3	G40 Hop Filter	10955
4	G40 Controller	10834
5	G40 Boiler Body	N/A
6	G40 Pump	10833
7	Power Box	N/A
8	G40 Plastic Base (NZ/AU/UK/EU)	10959
8	G40 Plastic Base (US)	10960
9	G40 Support Ring Retainer	10926
10	G40 1/2" Right Angle Ball Valve	10843
11	Sight Glass/Recirculation Retention Nut	Refer to A
12	Recirculation Hose Barb Holder	Refer to B
13	G40 Recirculation & Sight Glass Pipework	10835
14	G40 Threaded Hose Barb	10951
15	1/2" T Connection Nut	Refer to A
16	Threaded T Connection	Refer to A
17	G40 1/2" T	10902
18	Sight Glass/Recirculation Bottom Seal	Refer to B
19	G40 T Section Blank Hex Cap	10836
20	G40 Lifting Bar	10838
21	Recirculation Hose & Barb	Refer to B
22	G40 Grain Plate	10837
23	G40 Grain Basket	10832
24	G40 Counterflow Wort Chiller	10840
25	G40 Power Cable (EU)	10914
25	G40 Power Cable (UK)	10915
25	G40 Power Cable (NZ/AU) 10A	10839
25	G40 Power Cable (NZ/AU) 15A	10845
25	G40 Power Cable (US)	10917
26	G40 Tap Adapter Set	10399
27	G40 Pump Hose Clamp	10905
A	G40 Nuts & Bolts Pack	10920
B	G40 Silicone & Seals Pack	10841

 **BREWING SYSTEM**

GRAINFATHER
3
YEAR WARRANTY