

ANATOMY DIAGRAM & PARTS LIST



LIST OF PARTS



HI, I'M THE G70²
& HERE ARE ALL
OF MY PARTS



1	Glass Lid	10907
2	Support Ring	10900
3	Support Ring Retainer	10926
4	Hop Filter	10955
5	Controller, Cable and M16 DC Connector	N/A
6	Body	N/A
7	M16 Socket	N/A
8	Pump	10911
9	Power Box (US)	10972
9	Power Box (UK)	10973
9	NZ/AU/EU & G70v2 EU Power Box (15A)	10974
10	Plastic Base (NZ/AU/UK/EU)	10959
10	Plastic Base (US)	10960
11	1/2 Right Angle Ball Valve	10843
12	Sight Glass/Recirculation Retention Nut	Refer to A
13	Recirculation Hose Barb Holder	Refer to B
14	1/2" T Connection Nut	Refer to A
15	Threaded Hose Barb	10951
16	Threaded T Connection	Refer to A
17	1/2" T	10902
18	Sight Glass/Recirculation Bottom Seal	Refer to B
19	Lifting Bar	10901
20	Recirculation Barb & Hose	11343
21	Grain Plate	10837
22	Grain Basket (includes plate)	10993
23	Counterflow Chiller	10929
24	Power Cable (EU)	10976
24	Power Cable (UK)	10977
24	Power Cable (NZ/AU) 15A	10845
24	Power Cable (US)	10979
25	Ball Valve Tap	10910
26	Pump Hose Clamp	10905
27	Tap Adapter Set	10399
A	Silicone & Seals Pack	10999
B	Nuts & Bolts Pack	10902

 **BREWING SYSTEM**

